

Accessories
for pad printing

Cleaning tape

for automatic pad cleaning
and for pad cleaning by hand



The surface of the printing pad is a decisive factor for an optimal printing result. It should be free from impurities and left-over ink. With the cleaning tape from Teca-Print the pad surface is cleaned reliably and prepared for printing.


The adhesive force of the cleaning tape is critically important: it must be sufficiently strong in order to pick up the impurities but glue particles may not be left on the pad.

The Teca-Print cleaning tapes have been through many tests and optimised for pad printing.


The adhesion strength corresponds exactly to the required force and is also coordinated with the power of our automatic pad cleaning.

The cleaning tape is available in two different qualities: the cleaning tape "Standard" with a fine crepe structure or the transparent cleaning tape in quality "Extra" for the highest demands. Both variants are suitable for applications with our automatic pad cleaning device and for pad cleaning by hand.

Quality Standard



Quality Extra



	90 09 15	
	58594 0014	
	58594 0013	
	58594 0007	
	55479 0002	

	55479 0003	
	55479 0004	
	55479 0005	
	55479 0006	
	55479 0001	
	55479 0007	